




# MSFC Analysis of Thermal Control Materials on MISSE

## Post-Flight MISSE AZ-70-WIZT Inorganic White Thermal Control Coating



Note: 2-E8-7 and 2-E8-8 had epoxy applied because of chalking during vibration testing